

From: lukasz_k
Sent: Monday, July 26, 2010 4:30 PM
To: McCaughtry/Mary; ResnickL
Subject: August PBSB Meeting
Attachments: Street Light Obstructions.xlsx

Lisa,

Please add to power point. The map I reference is Proposed Roadway Lighting Diagram in the Wilson Miller Report. If you can't put in the agenda disregard the reference to the map in the text below.

Street Light Obstruction Recommendations

After review of the street lighting obstructions a list was made with the recommended modification which closely follow the recommendations of Wilson Miller. This list is included in the agenda package along with a map identifying the pole locations. Below is the total costs for the recommended modifications that include either pole relocation or tree/palm removal. An addition 42 lights had further pruning performed to enhance lighting effectiveness.

12 – Poles Relocated	\$ 27,300
45 – Trees/Palms Removed	\$ 7,350
	\$34,650

Under Florida Law, e-mail addresses are public records. If you do not want your e-mail address released in response to a public records request, do not send electronic mail to this entity. Instead, contact this office by telephone or in writing.

Street Light Obstructions - Tree/palm Removal

Fixture Number	Obstruction	Recommended Action	
102	103	2 - Sable Palms	Remove
104	105	2 - Sable Palms	Remove
108	109	1 - Sable Palm	Remove
114	115	1 - Sable Palm	Remove
118	119	2 - Sable Palms	Remove
122	123	1 - Sable Palm	Remove
134	135	1 - Sable Palm	Remove
136	137	2 - Sable Palms	Remove
138	139	Oak Canopy	Remove
144	145	1 - Sable Palm	Remove
146	147	1 - Sable Palm	Remove
156	157	2 - Sable Palms	Remove
158	159	1 - Sable Palm	Remove
162	163	2 - Sable Palms	Remove
164	165	1 - Sable Palm	Remove
192	193	2 - Sables	Remove
198	199	1 - Sable Palm	Remove
206	207	2 - Sable Palms	Remove
208	209	2 - Sable Palms	Remove
212	213	2 - Sable Palms	Remove
214	215	1 - Sable Pam	Remove
218	219	1 - Sable	Remove
232	233	Sable Palm, Tababu	Remove 3 Sable, Reloc PI
260	261	1 - Sable Palm	Remove
612	613	1 - Sable Palm	Remove
614	615	1 - Sable Palm	Remove
622	623	2 - Sable Palms	Remove
628	629	1 - Sable Palm	Remove
636	637	1 - Sable Palm	Remove
700	701	1 - Sable Palm	Remove
730	731	1 - Sable Palm	Remove
900	901	1 - Sable Palm	Remove

Street Light Obstruction - Pole Relocation

Fixture Number	Obstruction	Recommended Action
152	153 Oak Canopy	Move Pole
166	167 Oak Canopy	Move Pole
196	197 Sables	Relocate Pole to S. Med
216	217 Oak Canopy	Relocate Pole 30' South
224	225 Oak Canopy	Relocate Pole 30' N
232	233 Sable Palm, Tababu	Remove 3 Sable, Reloc
254	255 Oak Canopy	Reloca. Pole 10'W, Prune
704	Oak	Relocate Pole Across St
706	Oak	Relocate Pole 20' N
720	721 Sables	Relocate Pole 10' S
722	723 Sables	Relocate Pole 20' N
830	Oak	Relocate Pole Across St

August 4, 2010 – 9 a

Pelican Bay Services Division Board Regular Session
Update on Tree Trimming for Lighting

Page 4 of 4

